

Installation and Controlling

Step-by-step Installation Procedure (Software)

Warning:

Do not connect the Muk-Programmer to your OC before the installation of the Muk-Programmer-Software



1. Quit all programmes and insert the CD
 - The CD will start an automatic installation.
 - If your autorun-function has been disabled the installation should be done manually.
Select the "Configuration_Package" folder at the CD and run the exe-file .
2. During installation you will be prompted for
 - Userrights for the software
 - Folder name for the Muk-Programmer- Software installation
3. Afhter the installation, the Muk-Programmer-Software will start automatically.
4. Open the Help/Contens in the Muk-Programmer-Software and follow the instructions very carefully.

Charging of battery

Warning

Do not connect the Muk-Programmer to the PC before the USB-driver has been installed.

1. Connect the Muk-Programmer to your PC to insure that the battery will be charged.
2. The battery will be discharged if the Muk-Programmer is not connected to a PC for some time.
3. It takes 16 hours to fully charge the Muk-Programmer.
4. When receiving the Muk-Programmer it is maybe necessary to charge it before use.